TECH SHEET

PRCH36136 Liquid Mask

APPLICATION INSTRUCTIONS:

SPRAY GUN AND PRESSURE:

Gun Type Fluid Tip Air Pressure

Siphon Feed 1.8-2.0mm 40-50 psi

Gravity Feed 1.8-2.0mm 35-45 psi

HVLP 1.8-2.0mm 10 psi

Clean gun and dry thoroughly before storing gun to avoid corrosion of internal parts.

DIRECTIONS FOR USE:

- 1. Mask off surface to be painted with masking paper.
- 2. Apply one full wet coat of liquid mask on area to be protected.
- 3. Let dry for 20 to 30 minutes.
- 4. Remove any liquid mask overspray from surface to be painted.
- 5. Prepare the surface for painting as usual.
- 6. Apply primer, paint and/or clear and let cure as per manufacturers recommendations.
- 7. Once painting and buffing process is completed and cured, simply wet vehicle with water, allow to stand for 1-2 minutes before washing.

DRY TIME: 20 to 30 minutes at 18-24°C (65-75°F)

BAKING: Prch36136 can withstand baking temperatures of 76°C (150°F) without losing its effectiveness.

CAUTION: Do not use on fabric or fabric covered roofs.