

POLISHING PROCESS





DEFECT REMOVAL

Use: Microstar® P1500 with 5mm interface pad. Operate sander at medium speed (7000 - 8000 RPM).







Replace Microstar® with Polarstar® for extremely hard paint & gel coats.



Use: Abralon® P3000, damp or wet sanding. Operate sander at lower speed (5000 - 6000 RPM).





Use: Polarshine® 10 (finer) w/ 100% lambs wool pad. Operate buffer at moderate speed (1000 - 1500 RPM).





Use: Polarshine® 5 Cut & Gloss with Black Dot foam pad for efficient hologram removal. Final wipe and inspection with soft micro fiber cloth.



MIRKA COMPLETE SANDING SYSTEM:








• Polarstar ®



MIRKA® DEROS



Vacuum hoses









MIRKA ACCESSORIES









Polishing Foam Pads



Polishing Pads



Pneumatic Sanders



